



**HERSHEY** HERSHEY, PENNSYLVANIA

OWNER Hershey Foods | LOCATION Hershey, PA | FACILITY TYPE Food manufacturer

### PROJECT BACKGROUND

Hershey is the leading manufacturer of chocolate in North America. The main manufacturing plant, located in Hershey, Pennsylvania, was established in 1905 and since then has served as their company headquarters. Cocoa bean roasting and processing equipment became obsolete and unused on four floors of Building 38. Hershey decided to utilize this space for warehousing. Brandenburg was contracted to remove the old equipment while preserving the historic structure.

### SCOPE OF WORK

Removed all asbestos-containing material

Constructed negative air containments around insulated ovens

Verified and removed utilities

Disassembled, rigged, and removed select machinery to be scrapped

Removed all associated utility pipe, pipe hangers, and supports

Removed all associated process piping, chutes, and duct work

Constructed covers or perimeter guarding for all voids left in floors and walls

